

8

7

6

5

4

3

2

1

THIS DRAWING IS UNRESTRICTED.

RECEIVED FOR PRECIFICATION

20%

© COPYRIGHT 2024

TEC Electronics AMP GmbH

ALL RIGHTS RESERVED

417

2367105-6

A

5

CuSn4

0.35-0.5
FLR

1.1-1.4

E = 2.4
G = 2.3
D_{Dr} = 1.0

H = 2.9
K = 2.9
D = 1.4

2.5

3.8

5.7

18.8

0.2

417

2367105-3

A

5

CuSn4

0.35-0.5
FLR

1.1-1.4

E = 2.4
G = 2.3
D_{Dr} = 1.0

H = 2.9
K = 2.9
D = 1.4

2.5

3.8

5.7

18.8

0.2

417

2367105-1

A

5

CuFe2

0.35-0.5
FLR

1.1-1.4

E = 2.4
G = 2.3
D_{Dr} = 1.0

H = 2.9
K = 2.9
D = 1.4

2.5

3.8

5.7

18.8

0.2

417

965901-1

A

1

CuSn4

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

965899-1

A

1

CuSn4

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

928876-1

A

1

CuSn4

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

927775-7

M

1

CuNi12Zn24

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

927775-6

M

1

CuSn4

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

927775-3

M

1

CuSn4

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

927775-1

M

1

CuFe2

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

928810-1

A

1

CuFe2

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

963884-1

A

1

CuSn4

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

927773-3

N

1

CuSn4

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

927773-1

N

1

CuFe2

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

2-927768-1

R

1

CuSn4

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

1-927768-1

R

1

CuFe2

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

927768-9

P

1

CuSn4

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

927768-8

P

1

CuFe2

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

927768-6

P

1

CuSn4

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

927768-3

P

1

CuSn4

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

927768-1

P

1

CuFe2

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

1719810-1

A

1

CuSn4

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

2-927771-2

N

1

CuSn4

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

2-927771-1

N

1

CuFe2

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

1-927771-1

N

1

CuSn4

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

927771-9

M

1

CuSn4

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

927771-8

N

1

CuSn4

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

927771-6

M

1

CuSn4

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

927771-3

M

1

CuSn4

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

927771-1

M

1

CuFe2

0.5-1.0
FLR

1.4-2.3

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 3.9
D = 1.8

3

4

5.5

18.8

0.4

417

2-927774-1

C

2

CuSn4

0.2-0.5
FLR

1.0-1.6

E = 2.1
G = 2.1
D_{Dr} = 0.8

H = 2.7
K = 2.8
D = 1.4

2.5

3.5

5.6

18.8

0.4

417

1-927774-1

C

2

CuFe2

0.2-0.5
FLR

1.0-1.6

E = 2.1
G = 2.1
D_{Dr} = 0.8

H = 2.7
K = 2.8
D = 1.4

2.5

3.5

5.6

18.8

0.4

417

927774-6

B

2

CuSn4

0.2-0.5
FLR

1.0-1.6

E = 2.1
G = 2.1
D_{Dr} = 0.8

H = 2.7
K = 2.8
D = 1.4

2.5

3.5

5.6

18.8

0.4

417

927774-3

B

2

CuFe2

0.2-0.5
FLR

1.0-1.6

E = 2.1
G = 2.1
D_{Dr} = 0.8

H = 2.7
K = 2.8
D = 1.4

2.5

3.5

5.6

18.8

0.4

417

927774-1

B

2

CuFe2

0.2-0.5
FLR

1.0-1.6

E = 2.1
G = 2.1
D_{Dr} = 0.8

H = 2.7
K = 2.8
D = 1.4

2.5

3.5

5.6

18.8

0.4

417

963708-1

B

2

CuFe2

0.08-0.2
Sonderleitung

1.5-1.8

E = 1.7
G = 1.7
D_{Dr} = 0.6

H = 3.1
K = 3.2
D = 1.6

2.5

3.7

5.9

18.8

0.4

417

969137-1

A

3

CuSn4

0.2-0.5
FLR

1.2-2.3

E = 2.1
G = 2.1
D_{Dr} = 0.8

H = 3.5
K = 3.6
D = 2

2.5

3.5

5

18.8

0.4

417

1-927778-1

D

3

CuFe2

0.2-0.5
FLR

1.2-2.3

E = 2.1
G = 2.1
D_{Dr} = 0.8

H = 3.5
K = 3.6
D = 2

2.5

3.5

5

18.8

0.4

417

927778-3

C

3

CuSn4

0.2-0.5
FLR

1.2-2.3

E = 2.1
G = 2.1
D_{Dr} = 0.8

H = 3.5
K = 3.6
D = 2

2.5

3.5

5

18.8

0.4

417

927778-1

C

3

CuFe2

0.2-0.5
FLR

1.2-2.3

E = 2.1
G = 2.1
D_{Dr} = 0.8

H = 3.5
K = 3.6
D = 2

2.5

3.5

5

18.8

0.4

417

2112132-1

A

4

CuSn4

0.2-0.5
FLR

1.15-1.6

E = 2.4
G = 2.3
D_{Dr} = 1

H = 2.9
K = 2.9
D = 1.4

2.5

3.5

5.6

18.8

0.2

417

2-927766-1

E

5

CuSn4

0.5-1.0
FLR

1.4-2.1

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 4.6
D = 3.2

3

5.4

7

21

0.6

417

1-927766-1

E

5

CuFe2

0.5-1.0
FLR

1.4-2.1

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 4.6
D = 3.2

3

5.4

7

21

0.6

417

927766-3

D

5

CuSn4

0.5-1.0
FLR

1.4-2.1

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 4.6
D = 3.2

3

5.4

7

21

0.6

417

927766-1

D

5

CuFe2

0.5-1.0
FLR

1.4-2.1

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 4.6
D = 3.2

3

5.4

7

21

0.6

417

2-929937-1

E

5

CuSn4

0.5-1.0
FLR

1.4-2.1

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 4.6
D = 3.2

3

5.4

7

21

0.6

417

1-929937-1

E

5

CuFe2

0.5-1.0
FLR

1.4-2.1

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 4.6
D = 3.2

3

5.4

7

21

0.6

417

929937-6

E

5

CuSn4

0.5-1.0
FLR

1.4-2.1

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 4.6
D = 3.2

3

5.4

7

21

0.6

417

929937-3

E

5

CuFe2

0.5-1.0
FLR

1.4-2.1

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 4.6
D = 3.2

3

5.4

7

21

0.6

417

929937-1

E

5

CuSn4

0.5-1.0
FLR

1.4-2.1

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 4.6
D = 3.2

3

5.4

7

21

0.6

417

2-929939-1

E

5

CuSn4

0.5-1.0
FLR

1.4-2.1

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 4.6
D = 3.2

3

5.4

7

21

0.6

417

1-929939-1

E

5

CuFe2

0.5-1.0
FLR

1.4-2.1

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 4.6
D = 3.2

3

5.4

7

21

0.6

417

929939-6

E

5

CuSn4

0.5-1.0
FLR

1.4-2.1

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 4.6
D = 3.2

3

5.4

7

21

0.6

417

929939-3

E

5

CuFe2

0.5-1.0
FLR

1.4-2.1

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 4.6
D = 3.2

3

5.4

7

21

0.6

417

929939-1

E

5

CuSn4

0.5-1.0
FLR

1.4-2.1

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 4.6
D = 3.2

3

5.4

7

21

0.6

417

2-927770-1

G

5

CuSn4

0.5-1.0
FLR

1.4-2.1

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 4.6
D = 3.2

3

5.4

7

18.8

0.6

417

1-927770-1

G

5

CuFe2

0.5-1.0
FLR

1.4-2.1

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 4.6
D = 3.2

3

5.4

7

18.8

0.6

417

927770-6

F

5

CuSn4

0.5-1.0
FLR

1.4-2.1

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 4.6
D = 3.2

3

5.4

7

18.8

0.6

417

927770-3

F

5

CuFe2

0.5-1.0
FLR

1.4-2.1

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 4.6
D = 3.2

3

5.4

7

18.8

0.6

417

927770-1

F

5

CuSn4

0.5-1.0
FLR

1.4-2.1

E = 2.6
G = 2.8
D_{Dr} = 1.1

H = 3.6
K = 4.6
D = 3.2

3

5.4

7

18.8

0.6

417

2-929941-1

E

6

CuSn4

0.2-0.5
FLR

1.15-1.6

E = 2.1
G = 2.1
D_{Dr} = 0.8

H = 5.4
K = 4.6
D = 3.2

2.5

4.9

6.5

21

0.9

417

1-929941-1

E

6

CuFe2

0.2-0.5
FLR

1.15-1.6

E = 2.1
G = 2.1
D_{Dr} = 0.8

H = 5.4
K = 4.6
D = 3.2

2.5

4.9

6.5

21

0.9

417

929941-6

D

6

CuSn4

0.2-0.5
FLR

1.15-1.6

E = 2.1
G = 2.1
D_{Dr} = 0.8

H = 5.4
K = 4.6
D = 3.2

2.5

4.9

6.5

21

0.9

417

929941-3

D

6

CuFe2

0.2-0.5
FLR

1.15-1.6

E = 2.1
G = 2.1
D_{Dr} = 0.8

H = 5.4
K = 4.6
D = 3.2

2.5

4.9

6.5

21

0.9

417

929941-1

D

6

CuSn4

0.2-0.5
FLR

1.15-1.6

E = 2.1
G = 2.1
D_{Dr} = 0.8

H = 5.4
K = 4.6
D = 3.2</

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

[TE Connectivity:](#)

[927770-1](#)